ECS Configuration Change Request

1. Originator Sarah Lewallen	2. Log Date: **10/03/03**	3. CCR #: **03-0680**	4. Rev: —	5. Tel: 301-925-0865	6. Rm #: 3103A	7. Dept. SE

8. CCR Title: VERITAS Volume Manager 3.5 for SUN Consolidation Hosts

9. Originator Signature/Date **Sarah Lewallen /s/ 10/01/03**	10. Class **II**	11. Type: **CCR**	12. Need Date: 10/10/03

13. Office Manager Signature/Date **Carolyn Whitaker /s/ 10/02/03**	14. Category of Change: Update ECS Baseline Doc.	15. Priority: (If "Emergency" fill in Block 27). Routine

16. Documentation/Drawings Impacted *(Review and submit checklist)*: 920-TDx-002	17. Schedule Impact: None	18. CI(s) Affected:ACMHW

19. Release Affected by this Change: 6A, 6B	20. Date due to Customer:	21. Estimated Cost: None - Under 100K

22. Source Reference: ☐NCR (attach) ☐Action Item ☐Tech Ref. ☐GSFC ☒Other:
ESD 189

23. Problem: (use additional Sheets if necessary)
Need version of Volume Manager supported on Sun Fire family of hardware.

24. Proposed Solution: (use additional sheets if necessary)
Install Volume Manager 3.5 on the Sun Fire family of hardware.

25. Alternate Solution: (use additional sheets if necessary)
Configure as independent disks.

26. Consequences if Change(s) are not approved: (use additional sheets if necessary)
Will not be able to use software RAID.

27. Justification for Emergency (If Block 15 is "Emergency"):

28. Site(s) Affected: ☐EDF ☒PVC ☒VATC ☒EDC ☒GSFC ☒LaRC ☒NSIDC ☐SMC ☐AK ☐JPL
☐EOC ☐ IDG Test Cell ☐Other

29. Board Comments:	30. Work Assigned To:	31. CCR Closed Date:

32. EDF/SCDV CCB Chair (Sign/Date): **Byron V. Peters /s/ 10/07/03**	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS
33. M&O CCB Chair (Sign/Date):	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS
34. ECS CCB Chair (Sign/Date):	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS